


## Dust Monitoring Results MD-01 09/10/2019



Monitoring Location: North site perimeter between FD-01 and FD-02

